

## **Additional Funding Request**

Submitted: **6/16/2022**

<b>MD066 Air Handler Leaking</b>	<b>CSS #560 WO#17757</b>								
Description of Repairs	S&S proposes to remove and replace (2) control boards in the Daikin Unit. HP 2-17. S&S will then complete a system check to ensure everything is working properly.								
Original SC Investigative Diagnosis	<b>\$450.00</b>								
Diagnosis: Initial Work Order	Air handler leaking water in room 208, Repair leaks and Replace ceiling tiles. Get info on ceiling tiles*								
Explanation of Additional Costs for Repairs	N/A								
Additional Material Cost to Perform Repairs	<p><b>Materials: \$720.97</b></p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;"><b>ITEM</b></th> <th style="text-align: left; padding: 2px;"><b>QUANTITY</b></th> <th style="text-align: left; padding: 2px;"><b>UNIT PRICE</b></th> <th style="text-align: left; padding: 2px;"><b>TOTAL</b></th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;"><b>Parts detailed in Quote</b></td> <td style="text-align: center; padding: 2px;"><b>1</b></td> <td style="text-align: right; padding: 2px;"><b>\$720.97</b></td> <td style="text-align: right; padding: 2px;"><b>\$720.97</b></td> </tr> </tbody> </table>	<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>	<b>Parts detailed in Quote</b>	<b>1</b>	<b>\$720.97</b>	<b>\$720.97</b>
<b>ITEM</b>	<b>QUANTITY</b>	<b>UNIT PRICE</b>	<b>TOTAL</b>						
<b>Parts detailed in Quote</b>	<b>1</b>	<b>\$720.97</b>	<b>\$720.97</b>						
Additional Labor Cost to Perform Repairs	<p><b>Labor: \$1,200.00</b>            12 hours each/HVAC Rate \$100.00 per hour = \$1,200.00</p>								
<b>Total Cost of Repair</b>	<b>\$2,370.97</b>								