

## **Additional Funding Request**

Submitted **6/6/2021**

<b>MD066 - HVAC Not working 2nd floor</b>	<b>CSS #866 WO#17794</b>								
Description of Repairs	S&S proposes to replace the flow sensor on piping system. S&S will then complete a system check to ensure everything is working properly.								
Original SC Investigative Diagnosis	<b>\$400.00</b>								
Diagnosis: Initial Work Order	HVAC is not working properly, rooms on the second floor are warm								
Explanation of Additional Costs for Repairs	N/A								
Additional Material Cost to Perform Repairs	<p><b>Materials: \$ 858.56</b></p> <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;"><b>Paddlewheel Flow Sensor Flowmeter</b></td><td style="text-align: left; padding: 2px;"><b>1</b></td><td style="text-align: left; padding: 2px;"><b>\$858.56</b></td><td style="text-align: left; padding: 2px;"><b>\$858.56</b></td></tr> </tbody> </table>	ITEM	QUANTITY	UNIT PRICE	TOTAL	<b>Paddlewheel Flow Sensor Flowmeter</b>	<b>1</b>	<b>\$858.56</b>	<b>\$858.56</b>
ITEM	QUANTITY	UNIT PRICE	TOTAL						
<b>Paddlewheel Flow Sensor Flowmeter</b>	<b>1</b>	<b>\$858.56</b>	<b>\$858.56</b>						
Additional Labor Cost to Perform Repairs	<p><b>Labor: \$900.00</b>  9 hours each/HVAC Rate \$100.00 per hour = \$900.00</p>								
<b>Total Cost of Repair</b>	<b>\$2,158.56</b>								