

Additional Funding Request

Submitted: **5/11/2022**

MD066-LIGHTING	CSS #98 WO#17317											
Description of Repairs	S&S proposes to remove and replace the faulty emergency ballast in the wall pack light located in the mechanical room of the OMS building. *Lead time 3-4 weeks											
Original SC Investigative Diagnosis	\$300.00											
Diagnosis: Initial Work Order	Wall pack light above the Mechanical Room of the OMS building is flashing											
Explanation of Additional Costs for Repairs	N/A											
Additional Material Cost to Perform Repairs	Materials: \$ 622.64 <table border="1" style="width: 100%; border-collapse: collapse;"> <thead> <tr> <th style="text-align: left; padding: 2px;">ITEM</th> <th style="text-align: left; padding: 2px;">QUANTITY</th> <th style="text-align: left; padding: 2px;">UNIT PRICE</th> <th style="text-align: left; padding: 2px;">TOTAL</th> </tr> </thead> <tbody> <tr> <td style="text-align: left; padding: 2px;">Parts and Shipping detailed in attached Quote</td> <td style="text-align: center; padding: 2px;">1</td> <td style="text-align: right; padding: 2px;">\$622.64</td> <td style="text-align: right; padding: 2px;">\$622.64</td> </tr> </tbody> </table>				ITEM	QUANTITY	UNIT PRICE	TOTAL	Parts and Shipping detailed in attached Quote	1	\$622.64	\$622.64
ITEM	QUANTITY	UNIT PRICE	TOTAL									
Parts and Shipping detailed in attached Quote	1	\$622.64	\$622.64									
Additional Labor Cost to Perform Repairs	Labor: \$600.00 6 hours each/Electrical Rate \$100.00 per hour = \$600.00											
Total Cost of Repair	\$1,522.64											