

## Additional Funding Request

Submitted: 1/26/2022

<b>MD066 – Door lock set</b>	<b>CSS #34204 WO#16406</b>
Description of Repairs	<b>Problem:</b> Double door going from the supply area to the motor pool area is not working properly, not always locking, this is a physical security issue and needs to be repair
Diagnosis: Initial Work Order	S&S proposes to remove and replace the lock set on the double doors going to the supply area.
Explanation of Additional Costs for Repairs	S&S proposes to remove and replace the lock set on the double doors going to the supply area
Investigative Diagnosis fee from SC	<b>Diagnostic Total: \$160.00</b>
Additional Material Cost to Perform Repairs	<b>Material: \$816.00- PDQ EXIT DEVICE TRIM</b> <b>Shipping: \$50.00</b>
Additional Labor Cost to Perform Repairs	<b>Labor: \$640.00</b> <b>8 Hours x \$80 per hour</b> <b>General Maintenance Labor Rate</b>
<b>Total Cost</b>	<b>\$1,666.00</b>