

Additional Funding Request

Site: NY023	WO# 26719 CSS # 10263 Asset# NA
Description of Repairs	Remove and replace with LED lighting fixtures in Building 123
Diagnosis: Initial Work Order CSS# 10263	Fix ceiling light fixture in supervisor's office, B123
Explanation of Additional Costs for Repairs	3 hours on incurred diagnostic labor, needed lift and scaffold
Additional Labor Cost to Perform Repairs	X1 men at 7 hours x 125.00 –875.00
Additional Material Cost to Perform Repairs	LED 2x2 lighting fixture with bulbs = 302.00
Total Cost of Repair	\$1177.00

MSL Electric, LLC

6555 GRAND AVE
NY 11378

Estimate

Date	Estimate #
10/1/2020	1211

Name / Address

International Support Group
9050 Pine Blvd., Suite 150
Pembroke Pines, FL 33024