

Additional Funding Request

Site: NY023	WO#	CSS # 16617	Asset# NA
Description of Repairs	Replace contact relay		
Diagnosis: Initial Work Order CSS# 16617	Replace contact relay for exhaust system		
Explanation of Additional Costs for Repairs	Labor and material to replace contact relay for exhaust system		
Additional Labor Cost to Perform Repairs			
Additional Material Cost to Perform Repairs	\$988.73		
Total Cost of Repair	\$988.73		