

Additional Funding Request

Site: NY023	CSS # 17353 WO-2-3167
Description of Repairs	Replace (1) Pushbar Motor Kit Sargent M56AF
Diagnosis: Initial Work Order CSS# 20426	Fix Panic bar on main entrance to AMSA Building #123
Explanation of Additional Costs for Repairs	Labor and Material Fix Panic bar on main entrance to AMSA Building #123
Additional Labor Cost to Perform Repairs	$8 \times \$75.00 = \600.00 Incurred Cost = 550.00 Total Labor Cost \$1150.00
Additional Material Cost to Perform Repairs	\$445.37
Total Cost of Repair	\$1595.37
Notes:	Incurred Cost of 550.00 on approved AFR

LoCurrent Systems, LLC
3522 County Highway 11
Cooperstown, NY 13326
(607)293-7300
locurrent@gmail.com



Estimate

ADDRESS

ISG International Support Group

ESTIMATE # 1456**DATE** 10/24/2019**P.O. NUMBER**

Ft. Totten, NY AMSA Pushbar

	ACTIVITY	QTY	AMOUNT
10/24/2019	Services CSS#17353 Follow Up Quotation for Invoice #1523 Ft. Totten, NY USARC NY023 AMSA Main Entrance Pushbar	1	1,045.37

Dear Ms. DuBois:

As per your request, LoCurrent Systems is pleased to provide a Follow Up Quotation to replace Pushbar Motor at the Ft. Totten, NY USARC NY023 AMSA Bldg. 123 Main Entrance for proper operation.

Cost Breakdown:

(1) Pushbar Motor Kit Sargent
M56AF.....\$445.37
(1) man 8 hours
@\$75.....\$600.00

Grand
Total.....\$1,045.37

The cost for the above mentioned work is \$1,045.37.

If acceptable, please do not hesitate to contact us so we may schedule for work to be completed.

Thank you for thinking of LoCurrent Systems.

Sincerely,

Antonietta LoRusso

TOTAL

\$1,045.37

Accepted By

Accepted Date

CERTIFICATION OF WORK
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID Building: Ft. Totten, NY USARC NY023 Date of Visit: 10/24/2019

Contractor Personnel on Site:

1.	Nicholas LoRusso	4.
2.	Kenneth Stahl	5.
3.		6.

Service Calls – Service Call Number and Description

1. CSS#17353 Invoice #1523 Diagnose Main Entrance Panic Bar at Ft. Totten, NY USARC NY023.
2. Removed Door Hardware & Pushbar with Pushbar Motor intact and installed on functional location;
3. problem followed. Pushbar and Motor are cause of problem. Pushbar Motor needs to be replaced. LoCurrent Systems shall provide Follow Up Quotation for repair/replacement of necessary equipment for proper operation.

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Nicholas LoRusso Date: 10/24/19

Signed: NR

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: Louis A. Cane AFOS Date: 10/24/19

Signed: Louis A. Cane

Email: Louis.A.Cane.CM@usaf.mil

