

Additional Funding Request

Site: NY023	WO# 18684 CSS # 1807
Description of Repairs	ACAV onsite, several Fan Coil are not working, Will require further diagnostic as it appears to be system related and not mechanical.
Diagnosis: Initial Work Order	Diagnose and repair A/C fan coil units on the third floor of building #206
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	8hrs@235.00 hr = \$1800.00
Additional Material Cost to Perform Repairs	
Total Cost of Repair	\$1800.00

ACAV SERVICES

July 22, 2022



ESTIMATE 072222 CSS1807

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 206)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	NY23 BLDG 206 3RD FLOOR FAN COIL UNITS FAN COIL UNITS NOT COOLING TROUBLE SHOOT AND REPAIR IF POSSIBLE <u>LABOR</u> 8 HRS @ \$235.00 PER HOUR TOTAL		\$1880.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

