

## Additional Funding Request

Site: NY058	WO# 18692 CSS # 1872
Description of Repairs	Respond to emergency service call, reset and perform diagnostic on pump station. Incurred cost for diagnostic performed, found second pump will need to be replaced with govt provided pump. Request new WO issued for submission or repair quote
Diagnosis: Initial Work Order	Repair pump station. Alarm continues to sound. Possible lighting strike
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	8hrs@250 <u>hr</u> = \$2000
Additional Material Cost to Perform Repairs	
Total Cost of Repair	\$2000.00

# ACAV SERVICES

July 27, 2022



ESTIMATE 072722 CSS1872

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 200)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	<b>NY23 BLDG 200 SEWER LIFT STATION</b> <b>LIFT STATION STRUCK BY LIGHTING</b> <b>EMERGENCY REPAIR TO REST CONTROLS AND RUN DIAGNOSTICS</b> <b>LABOR (EMERGENCY)</b> <b>8 HRS 2 \$250.00</b>  <b>NUMBER 2 SEWER PUMP FOUND NOT WORKING</b>		<b>\$2000.00</b>

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581



