

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 4710</b>	<b>CSS # 19796</b>	<b>Asset# NA</b>
Description of Repairs	Remove and replace existing LED lighting fixture		
Diagnosis: Initial Work Order <b>CSS# 19796</b>	Replace broken light fixture in hallway of building #118. Only light in hallway		
Explanation of Additional Costs for Repairs	Labor and material to remove and replace LED lighting fixture		
Additional Labor Cost to Perform Repairs	\$330.00 (Incurred) + \$220.00		
Additional Material Cost to Perform Repairs	\$178.00		
Total Cost of Repair	\$728.00		

**CERTIFICATION OF WORK**  
(To be completed by the Contractor and saved in the Contractor's CMMS)

FACID/Building: NY023 Date of Visit: 7/1/2019

Contractor Personnel on Site:

1. Michael Sarro 2. \_\_\_\_\_

**Work Performed:** *Investigate Lighting fixture in egress area Building 118*

**Preventive Maintenance - Services Completed (Annual, Quarterly, Monthly, equipment identification, etc.)**

1. WO# 2-4710

**Service Calls – Service Call Number and Description**

1. CSS# 19796  
2. CSS# \_\_\_\_\_  
3. CSS# \_\_\_\_\_

Pictures are required (Before and After)

---

**CERTIFICATION OF WORK**

---

To be signed by the Contractor:

Print Name: Michael Sarro Date: 7/1/2019

Signed: \_\_\_\_\_

To be signed by Facility Manager:

I certify that the above named individuals representing the Contractor arrived on site and to the best of my knowledge, completed the stated work listed:

Print Name/Rank: Louis Corbo Date: 7-1-19

Signed: Louis Corbo

E-Mail: Louis.192.Corbo@CITRUS.EDU.MAIL.COM

MSL Electric, LLC

6555 GRAND AVE  
NY 11378

## Estimate

Date	Estimate #
7/1/2019	1153

Name / Address

---

International Support Group  
9050 Pine Blvd., Suite 150  
Pembroke Pines, FL 33024

MSL Electric, LLC

6555 GRAND AVE  
NY 11378


# Invoice


Date	Invoice #
7/1/2019	1152

Bill To
International Support Group 9050 Pine Blvd., Suite 150 Pembroke Pines, FL 33024

P.O. No.	Terms	Project
WO 2-4708	Due on receipt	

Quantity	Description	Rate	Amount
3	Investigate defective egress lighting Building 118 Ft. Totten as per WO 4708 CSS 19819	110.00	330.00
			<b>Total</b> \$330.00





Ft. Totten WO 4708 Doorway to egress with Dffective Light Bld 118