

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 4718</b>	<b>CSS # 20077</b>	<b>Asset# NA</b>
Description of Repairs	Repair knocked over gooseneck (gooseneck will eventually need to be replaced. This is a temporary repair until new card reader is installed). As per instructions of facility manager-Ryan Linn.		
Diagnosis: Initial Work Order <b>CSS# 20077</b>	Main entrance keypad stand seems to have been hit by vehicle and left standing by cable wires only. Must build		
Explanation of Additional Costs for Repairs	Labor and material to repair gooseneck		
Additional Labor Cost to Perform Repairs	\$2,300.00		
Additional Material Cost to Perform Repairs	\$120.00		
Total Cost of Repair	\$2,420.00		



---

## **Proposal for Fort Totten Main Entrance Gate Repair**

July 3, 2019

To: International Support Group  
Attn: Mr. Mike Wolfe  
Email: [mwolfe@internationalgroup.com](mailto:mwolfe@internationalgroup.com)  
Location of Work: Building 200, Fort Totten, NY

### **Scope of Work**

- Repair knocked over gooseneck (gooseneck will eventually need to be replaced. This is a temporary repair until new card reader is installed). As per instructions of facility manager- Ryan Linn.

Estimate:	\$450.00
Material:	\$120.00
Labor:	<u>\$1,850.00</u>
Total Cost:	\$2,420.00

**QUOTATION VALID FOR:** 45 Days from Quotation Date

**ACCEPTANCE OF QUOTATION:**

The above prices, conditions and specification are hereby accepted. You are authorized to do the work as specified.

Client's Printed Name Acceptance: \_\_\_\_\_

Client's Authorized Signature of Acceptance: \_\_\_\_\_

Acceptance Date: \_\_\_\_\_



