

Additional Funding Request

Site: NY023	CSS # 22939 WO-2-6499
Description of Repairs	Diagnose repair MEP lot mechanical gate
Diagnosis: Initial Work Order CSS# 22939	Repair of MEP lot mechanical gate, broken section of HY Security Xtreme Drive Rack
Explanation of Additional Costs for Repairs	<p>Labor and Material to replace and repair three sections of HY Security Xtreme Drive Rack.</p> <ul style="list-style-type: none"> • Mobilization to the site with equipment needed (New Hy Security Xtreme Drive Rack Sections and tools needed to remove the existing broken sections and install new sections of Xtreme Drive Rack). • Remove and dispose of existing (3) broken Xtreme Drive Rack sections • Supply and install new (3) Hy Security Xtreme Drive Rack sections • Test gate operator for proper function • Clean up work area upon completion and demobilize
Additional Labor Cost to Perform Repairs	$1 \times \$600.00 = \600.00 Incurred Cost \$400.00 Total Labor \$1000.00
Additional Material Cost to Perform Repairs	\$507.50
Total Cost of Repair	\$1507.50
Notes:	

12-11-2019

Fort Totten - MEP Cantilever Gate Track Repair Quote

To: International Support Group
Attn: Ms. Michele Dubois (Site Supervisor)
Address: 9050 Pines Blvd., Suite 150, Pembroke Pines, FL 33024
Email: mdubois@internationalsupportgroup.com
Phone: (954) 900-1095

Location: Fort Totten, MEP Cantilever Slide Gate, Flushing, NY
RE: Service Request # CSS 22939, WO# 2-6499

URGENT ASSESSMENT COST:

- Sent out a project manager to respond to this Urgent Service Request. Our project manager arrived and contacted Mr. Louis Corbo from 99th RSC. After locating the issues, our project manager tried to repair the broken sections of HY Security Xtreme Drive Rack, but was unsuccessful (for three sections of this Xtreme Drive Rack need to be replaced. Our Project Manager will not be able to take care of the repairs under the \$450 limit repair site visit cost. We have included our assessment cost, along with the cost necessary to do the repairs needed.

Emergency Assessment Cost: 4 hours @ \$100 per hour = \$400

TOTAL EMERGENCY ASSESSMENT COST: \$400

Scope of Work:

- Mobilization to the site with equipment needed (New Hy Security Xtreme Drive Rack Sections and tools needed to remove the existing broken sections and install new sections of Xtreme Drive Rack).
- Remove and dispose of existing (3) broken Xtreme Drive Rack sections
- Supply and install new (3) Hy Security Xtreme Drive Rack sections
- Test gate operator for proper function
- Clean up work area upon completion and demobilize



12-11-2019

Fort Totten - MEP Cantilever Gate Track Repair Quote

BREAKDOWN OF COSTS:

ITEM DESCRIPTION	COST
Mobilization of equipment (New Hy Security Xtreme Drive Rack Sections and tools needed for removal of broken sections and installation of new sections)	\$100.00
(3) New Hy Security Xtreme Drive Racks sections	\$307.50
Demobilization of equipment	\$100.00
Labor Needed: 1 man x 6 hrs x \$100 per hour:	\$600.00
QUOTE TOTAL:	\$1,107.50

QUOTATION VALID FOR: 30 DAYS FROM QUOTATION DATE

ACCEPTANCE OF QUOTATION:

The above price, conditions and specifications are hereby accepted. You are authorized to do the work as specified. Payment schedule: Cost of all materials up front and balance upon completion of work.

QUOTE ACCEPTANCE:

Client's Printed Name: _____

Client's Acceptance Signature: _____

Date: _____