

Additional Funding Request

Site:	WO #23783 CSS #94380
Description of Repairs	Bldg. 206 1st Floor men's room cleaning closet sink. The hot water valve seat is leaking and needs to be shut off to make the repair.
Diagnosis: Initial Work Order	Repair/replace utility mop sink; commercial grade sink with a vacuum break built in needs to be replaced
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	1050.00
Additional Material Cost to Perform Repairs	770.00
Total Cost of Repair	1820.00

August 11, 2023



Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 206)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		<p>NY23 (BLDG 206) 1ST FLOOR MENS LATRINE CUSTODIAL CLOSET/SINK</p> <p>REPAIR/REPLACE UTILITY (MOP SINK)</p> <p>THIS IS A COMMERCIAL GRADE SINK WITH A VACUUM BREAK BUILT IN IT NEEDS TO BE REPLACED</p> <p><u>MATERIAL</u></p> <p>1 EA SERVICE FAUCET FOR MOP SINK W VACUUM BREAKER</p> <p>2 EA 3/4" SPEEDY VALVE CONNECTORS</p>		<p>\$520.00</p> <p>\$100.00</p>

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		MISC PIPE AND FITTINGS		\$150.00
		<u>TOTAL MATERIAL</u>		\$770.00
		<u>LABOR</u>		
		5 HRS @ \$210.00 PER HOUR		\$1050.00
		TOTAL		\$1820.00
		NOTE: THE MAIN WATER VALVE IN THIS BUILDING IS VERY OLD AND WILL NEED TO BE TURNED OFF FOR THE REPAIR. THE VALVE MAY NEED TO BE REPLACED WHICH WOULD BE AN ADDITIONAL EXPENSE		
			TOTAL	\$1820.00



