

Additional Funding Request

Site: NY0023	WO# 7915 CSS # 24595 Asset# NA
Description of Repairs	Overhead door in OMS broken, won't close
Diagnosis: Initial Work Order CSS# 23185	Electric Gate is jammed all the way up inside housing
Explanation of Additional Costs for Repairs	Secure brush on top, secure hanging loose cover, repair damaged bottom rail, install on one side weather seal rubber on track, set limit switch and general maintenance
Additional Labor Cost to Perform Repairs	
Additional Material Cost to Perform Repairs	
Total Cost of Repair	\$1250.00