

Additional Funding Request

Site: NY023	WO# 10312 CSS # 26808 Asset# NA
Description of Repairs	Additional fund request for more extensive diagnostic. Initial investigation found two fuses that were open (blown). This usually means there is a dead short in one of the conduits and all the lighting pole splices will need to be disconnected in order to analyze where the problem exists. After the diagnostics is completed, a more thorough answer can be obtained to assist in the best solution
Diagnosis: Initial Work Order CSS# 26808	Diagnose and repair the MEP Lighting in back lot.
Explanation of Additional Costs for Repairs	3 Fuses At 125.00= 375.00 misc material 56.00 = 431.00
Additional Labor Cost to Perform Repairs	X1 men at 8hours x 125.00 – 1000.00
Additional Material Cost to Perform Repairs	431.00
Total Cost of Repair	1431.00

MSL Electric, LLC

6555 GRAND AVE
NY 11378

Estimate

Date	Estimate #
10/1/2020	1208

Name / Address

International Support Group
9050 Pine Blvd., Suite 150
Pembroke Pines, FL 33024