

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 10313 CSS # 26899 Asset# NA</b>
Description of Repairs	Replace (4) rollers and realign main quides, repair frayed wire on controller, align contacts and rehang gate and lubricate
Diagnosis: Initial Work Order <b>CSS# 26899</b>	Diagnose and repair MEP Gate will not close automatically
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	X2 men at 2hours_ 4hrs x 165.00 = 660.00
Additional Material Cost to Perform Repairs	375.00
Total Cost of Repair	\$1035.00

# ACAV SERVICES

October 2, 2020



ESTIMATE 100120 CSS26899 WO10313

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW R Linn
Customer ID#	NY023 (BLDG 200)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	CC	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	<p><b>NY023 AMSA</b></p> <p><b>MEP PARKING LOT MOTORIZED GATE</b></p> <p><b>DIAGNOSE GATE</b></p> <p><b>REPLACE 4 ROLLERS</b></p> <p><b>REALIGN MAIN GUIDES</b></p> <p><b>REPAIR FRAYED WIRE ON CONTROLLER</b></p> <p><b>ALIGN CONTACTS</b></p> <p><b>REHANG GATE AND LUBRICATE</b></p>		

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		<b>4 EA ROLLERS</b>		
		<b>2 EA NEW U CLAMPS</b>		
		<b>MISC HARDWARE</b>		
		<b>TOTAL MATERIAL</b>		<b>\$375.00</b>
		<b>LABOR 4 HRS 2 \$165.00 PER HOUR</b>		<b>\$660.00</b>
		<b>TOTAL</b>		<b>\$1035.00</b>
		<b>NO TAX</b>		
				<b>TOTAL \$1035.00</b>