

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 24992 CSS # 27023 Asset# NA</b>
Description of Repairs	Repair two growing pot holes outside of the exit gate of B200
Diagnosis: Initial Work Order <b>CSS# 27023</b>	Repair (2) two pot holes, saw cut, back fill with asphalt tamper
Explanation of Additional Costs for Repairs	3 hours on incurred diagnostic labor, needed lift and scaffold
Additional Labor Cost to Perform Repairs	4hrs @ 220.00 = \$880.00
Additional Material Cost to Perform Repairs	100 SQ FT of asphalt = \$225.00
Total Cost of Repair	\$1105.00

# ACAV SERVICES

October 9, 2020



ESTIMATE 100920 CSS27023 WO24992

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW R Linn
Customer ID#	NY023 (BLDG 200)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	CC	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	<b>NY023 FRONT GATE</b>  <b>REPAIR 2EA POT HOLES JUST OUTSIDE THE EXIT GATE</b>  <b>SAW CUT HOLES, BACK FILL WITH NEW ASPHALT TAMPER</b>  <b>MATERIAL</b>  <b>100 SQFT ASPHALT</b>		\$225.00
		  <b>LABOR</b>  <b>4HRS @ \$220.00</b>		\$880.00
		  <b>TOTAL</b>		<b>\$1105.00</b>

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581