

Additional Funding Request

Site: NY023	WO# 10697 CSS # 27524 Asset# NA
Description of Repairs	Remove gate, replace all hardware with new neoprene fittings, align contacts, rehang gate.
Diagnosis: Initial Work Order CSS# 27524	Repair automatic gate at entrance to MEP lot.
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	8 hours @ \$195.00 = \$1400.00
Additional Material Cost to Perform Repairs	\$195.00
Total Cost of Repair	\$1595.00

ACAV SERVICES

November 6, 2020



ESTIMATE 110620 CSS27524 WO10697

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW R Linn
Customer ID#	NY023 (BLDG 200)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	CC	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	NY023 AMSA MEP PARKING LOT MOTORIZED GATE DIAGNOSE GATE REMOVE GATE REPLACE ALL HARDWARE WITH NEOPRENE BOLTS AND FITTINGS ALIGNED CONTACTS REHANG GATE AND LUBRICATED TOTAL MATERIAL MISC HARDWARE LABOR 8 HRS @ \$175.00 PER HOUR TOTAL		\$195.00 \$1400.00 \$1595.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
TOTAL \$1595.00				