

Additional Funding Request

Site: NY023	WO# 6897 CSS # 27691
Description of Repairs	. It is not calibrated. The thermostat needs to be replaced in order for the unit to allow heat through the coil.
Diagnosis: Initial Work Order CSS# 27691	ASSET #190917-192 temperature control switch (thermostat) is not working properly
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	3.0 hrs @ \$85.00= \$255.00
Additional Material Cost to Perform Repairs	\$111.60
Total Cost of Repair	\$366.60

WORK ORDER ESTIMATE

CSS #:

Work Order #:

Emergency

Urgent

2

Routine

Company Name:	ISG	Facility ID:	NY023
Contractor POC:			
Telephone No:		Building/Location; (e.g., Classroom/Room #)	BUILDING 206
E-Mail Address:			
Assigned Technician(s):	Deen Rowe		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Asset#190917-192, no heat is coming from the units

ASSET #190917-192 temperature control switch (thermostat) is not working properly. It is not calibrated. The thermostat needs to be replaced in order for the unit to allow heat through the coil.

LABOR/MATERIAL		MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$85.00	LINE ITEM TOTAL DOLLAR AMOUNT
ITEM	QUANTITY			
DIAGNOSIS	1		\$85.00	\$85.00
LABOR	2		\$85.00	\$170.00
THERMOSTAT	1	\$111.60		\$111.60
SUB-TOTAL COSTS:		Materials Total	\$111.60	Labor \$255.00
		TOTAL		\$366.60

Heating/Cooling Control w/ 26" Capillary

SKU

C17-100

Brand

Ranco

Rating



\$85.16 each



ADD TO CART

In Stock

Get 17 **Mon, Nov 30**

More Available [Inventory Details](#) ▾



Fast Track

Order by **5PM**, receive by **Mon**

Free Shipping

Easy Returns