

Additional Funding Request

Site: NY023	WO# 12531 CSS # 29958
Description of Repairs	Control Button was disconnected from wiring and fallen out of switch plate. New connection made and reinstalled control button, Tested and operating properly
Diagnosis: Initial Work Order	Repair gate control button in guard shack at main gate
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	Locurrent Base Service call 600.00
Additional Material Cost to Perform Repairs	0.00
Total Cost of Repair	\$600.00

CERTIFICATION OF WORK

(To be completed by the Contractor and saved in the Contractor's CMMS)

FT. Totten, NY

FACID/Building: NY023

Date of Visit: April 16, 2021

Contractor Personnel on Site:

1. Nicholas LoRusso
2. _____
3. _____
4. CSS# 29958
5. WO# 12531
6. Estimate # 1772

Service Calls – Service Call Number and Description

1. Gate Control Button Main Gate Guard Shack
2. Button was disconnected from wiring and had
3. fallen out of switch plate. New connections made, button re-installed. Tested Functional.

CERTIFICATION OF WORK

To be signed by the Contractor:

Print Name: Nicholas LoRusso Date: 4/16/2021

Signed: Nicholas LoRusso

To be signed by Facility Manager:

By signing the Certification of Work, the said government representative signature does not constitute acceptance of any work performed by the contractor, it only acknowledges that the contractor was on-site during the identified timeline:

Print Name/Rank: _____ Date: _____

Signed: no personnel available at the

E-Mail: time of completion. Can confirm with Mr. Louis Corbo
↳ (917)405-71165



