

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 13973 CSS # 31180</b>
Description of Repairs	Removal of fixture in AMSA main office. Remove and replace with new LED light fixture.
Diagnosis: Initial Work Order	Repair light fixture in supervisor's office of AMSA 12. Light fixture is not a bulb fixture, it is powered by a circuit board
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	5 hours @ 125.00 includes two (2) hours of diagnostic- Total Labor \$625.00
Additional Material Cost to Perform Repairs	\$ 460.00
Total Cost of Repair	\$1085.00
	<b>This fixture is custom made and had an 8-10 week lead time</b>

MSL Electric, LLC

6555 GRAND AVE  
NY 11378

# Estimate

Date	Estimate #
7/8/2021	1256

Name / Address	Project
International Support Group 9050 Pine Blvd., Suite 150 Pembroke Pines, FL 33024	NY0023 Ft. Totten 123 Duane Road Bayside, NY 11359

Work Order	CSS	Terms
WO2-13973	31180	Net 30

Item	Description	Qty	Rate	Total
Service	Removal of fixture in AMSA main office and replacement with a new fixture of the same. This is an LED 2X2 fixture and the whole fixture must be removed and replaced with a new fixture. This fixture has to be custom build by the original manufacturer and has a lead time of 8-10 weeks.	3	125.00	375.00
16 Electrical & Li...	LED Lighting fixture for above repair.	1	460.00	460.00
Service	Diagnostics fee for above. The fixture is an LED type fixture and must be completely replaced as the driver and diodes are not replaceable in the field.	2	125.00	250.00
		<b>Subtotal</b> \$1,085.00		
		<b>Sales Tax (8.875%)</b> \$0.00		
		<b>Total</b> \$1,085.00		