

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 13980 CSS #31220</b>
Description of Repairs	Replace damaged return line on ceiling mounted coil unit.
Diagnosis: Initial Work Order	Repair overhead hot water return pipe in bay 11 of AMSA 12. Pipe is overhead and was hit with a forklift and has a slow drip despite closing the shutoff valve
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	8hrs @ 245.00 per hour = \$1960.00
Additional Material Cost to Perform Repairs	\$525.00
Total Cost of Repair	\$2485.00
	Quote is valid for 30 days

June 21, 2021



Qty.	Item#	Description	Unit Price	Line Total
1	1	NY023 AMSA (BAY 11)		
		REPLACE DAMAGED RETURN LINE ON CEILING MOUNTED COIL UNIT		
		<u>MATERIAL</u>		
		8FT 1" PIPE		
		4EA 90 DEGREE ELBOW'S		
		2EA COUPLINGS		\$525.00
		1EA REDUCING FLANGE		
		<u>LABOR</u>		
		8HRS @ \$245.00 PER HOUR		\$1960.00

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		<p><b>THIS REPAIR IS FOR THE RETURN LINE ONLY THE HEATING COIL MAY ALSO BE DAMAGED AND MAY REQUIRE ADDITIONAL REPAIRS</b></p> <p><b>THIS QUOTE WILL EXPIRE IN 30 DAYS</b></p> <p><b>TOTAL</b></p>		<p><b>\$2485.00</b></p>
TOTAL				<b>\$2485.00</b>

