

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 14923 CSS #32633</b>
Description of Repairs	Repair broken Mess Hall entrance metal door. Remove door , realign frame and install heavy duty piano hinge
Diagnosis: Initial Work Order	Repair kitchen exterior metal door and frame both have been bent and now stop door from closing.
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	5 hours at \$235.00= \$1175.00
Additional Material Cost to Perform Repairs	\$195.00
Total Cost of Repair	<b>\$1370.00</b>

# ACAV SERVICES

September 25, 2021



ESTIMATE 092521 CSS32633 WO14923

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW
Customer ID#	NY023 (BLDG 200)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	NY023 BLDG 200  <b>REPAIR BROKEN MESS HALL ENTRANCE (METAL DOOR)</b>  <b>REMOVE DOOR, REALIGN FRAME, INSTALL HEAVY DUTY PIANO HINGE</b>  <b><u>MATERIAL</u></b>  <b>72' HEAVY DUTY PIANO HINGE</b>		\$195.00
		<b><u>LABOR</u></b>  <b>5 HRS @\$235.00 PER HOUR</b>		\$1175.00
		<b>TOTAL</b>		<b>\$1370.00</b>

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581