

Additional Funding Request

Site: NY023	WO# 14934 CSS #32771
Description of Repairs	Repair storm fence in rear of building
Diagnosis: Initial Work Order	Reinstall storm fence at the back of Building #118. Two sections of the storm fence were taken down and have to be reinstalled
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	6 hours at \$225.00= \$1350.00
Additional Material Cost to Perform Repairs	\$450.00
Total Cost of Repair	\$1800.00

ACAV SERVICES

October 4, 2021



ESTIMATE 100421 CSS32771

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW
Customer ID#	NY023 (BLDG 118)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	NY023 BLDG 118		
		REPAIR STORM FENCE IN REAR OF BUDLING		
		<u>MATERIAL</u>		
		10FT STORM FENCING, 2EA POSTS AND GUIDE WIRE		\$\$450.00
		<u>LABOR</u>		
		6 HRS @ \$225.00 PER HOUR		\$1350.00
		TOTAL		\$1800.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581