

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 15194 CSS #32968</b>
Description of Repairs	Diagnosed a power issue with the Ductless AC unit in the CIPR NET room. Branch circuit for this unit is located on the third floor in panel 3007B. Unit is located on the first floor and condensing unit is located on the roof above Kane Hall. After locating the circuit breaker and re-energizing the circuit it was discovered the service disconnect switch at the unit was defective. This switch will need to be replaced.
Diagnosis: Initial Work Order	Diagnose and repair split unit in SIPR room on first floor of building # 200. There seems to be no power to the unit.
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	3.0 HRS @125.00 For repair- \$375.00 2.0 HR @ 125.00 for incurred diagnostic cost= \$250.00 Total Labor= \$625.00
Additional Material Cost to Perform Repairs	\$37.00
Total Cost of Repair	<b>\$662.00</b>

MSL Electric, LLC

6555 GRAND AVE  
NY 11378

# Estimate

Date	Estimate #
10/20/2021	1262

Name / Address	Project
International Support Group 9050 Pine Blvd., Suite 150 Pembroke Pines, FL 33024	NY0023 200 Duane Road Bayside, NY 11359

Work Order	CSS	Terms
32968	32968	Net 30

Item	Description	Qty	Rate	Total
Service	Diagnosing a power issue with the Ductless AC unit in the CIPR NET room. Branch circuit for this unit is located on the third floor in panel 3007B. Unit is located on the first floor and condensing unit is located on the roof above Kane Hall. After locating the circuit breaker and re-energizing the circuit it was discovered the service disconnect switch at the unit was defective. This switch will need to be replaced.	3	125.00	375.00
16 Electrical & Li...	Electrical material for above repair.	1	37.00	37.00
Service	Diagnostics Fee for above.	2	125.00	250.00
		<b>Subtotal</b> \$662.00		
		<b>Sales Tax (8.875%)</b> \$0.00		
		<b>Total</b> \$662.00		