

Additional Funding Request

Site: NY023	WO# 15541 CSS #33522
Description of Repairs	Replace light sensor switch in building 330 A room 121, light remains on.
Diagnosis: Initial Work Order	Removal of one wall occupancy sensor in Room 121 and an additional failed occupancy sensor in Room 110. Both to be replaced with new.
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	4 hours (including 2 hours diagnostic @ 125.00 per hour= \$500.00
Additional Material Cost to Perform Repairs	\$108.00
Total Cost of Repair	\$608.00

MSL Electric, LLC

6555 GRAND AVE
NY 11378

Estimate

Date	Estimate #
11/23/2021	1267

Name / Address
International Support Group 9050 Pine Blvd., Suite 150 Pembroke Pines, FL 33024

Project
NY0023 Ft.Totten 330 Pratt Avenue Bayside, NY 11359

Work Order	CSS	Terms
	33522	Net 30

Item	Description	Qty	Rate	Total
Service	Removal of one wall occupancy sensor in room 121 and replacement with a new Occupancy Sensor.	1	125.00	125.00
Service	Removal of one wall occupancy sensor in room 110 and replacement with a new Occupancy Sensor.	1	125.00	125.00
16 Electrical & Li... Service	Electrical Material for above repair. Diagnostics for above repair.	2	54.00	108.00
		2	125.00	250.00
		Subtotal \$608.00		
		Sales Tax (8.875%) \$0.00		
		Total \$608.00		