



ESTIMATE 121621 CSS33767 W015580

Bill To		Ship To		
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW	
Customer ID#	NY023 (MEP LOT)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY	
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188	
Phone	954 900 1095			
Payment Due	NET 30	Delivery Date	N/A	
Salesperson	JW	Shipping Method	N/A	
Payment Terms	N/A	Shipping Terms	N/A	

Qty.	Item#	Description	Unit Price	Line Total
1	1	<p>NY023 MEP PARKING LOT</p> <p>REPLACE DEFECTIVE LOWER DRIVE WHEEL ON HYSECURITY SYSTEMS GATE. REMOVE GATE INSTALL NEW ASSEMBLY AND REHANG GATE AND CHECK FOR PROPER ALIGNMENT</p> <p><u>MATERIAL</u></p> <p>HYS-MX002597 HYSECURITY 6" WHEEL AND DRIVE ASSEMBLY</p> <p><u>LABOR</u></p> <p>16 HRS @ \$190.00 PER HOUR</p> <p>(2 MEN 8HRS EACH)</p> <p>TOTAL</p>		<p>\$775.00</p> <p>\$3040.00</p> <p>\$3815.00</p>

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

Over and Above Estimate

Region: 2

Location: NY023

CSS #: 33767

Maximo Work Order No. 15580

Asset#:

Date Issued: 12/8/2021

Original Description: Repair broken motor sprocket on MEP lot gate motor. Broken sprocket is restricting motion of the gate.

Description of Repairs: Replace defective lower drive wheel on Hy security system gate. Remove gate Install new assembly and rehang gate. Check for proper alignment and operation.

Non Pre-Priced Estimate:

Quantity	Line Item #	Description	Labor Hours	Unit	Labor	Materials	Equipment	Total
1		Materials (See attached estimate for line items)				\$775.00	\$0	\$775.00

Note: RS Means (Pre-Priced) not used in compiling this estimate.

Note: Subcontractor quote attached.

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment Cost	Total Cost	CE Factor	Total Estimate
X2 men at 8 hours each total man hours 16 hrs @ \$190.00 = \$1800.00	\$3040.00	\$775.00		\$3815.00	.90%	\$3433.50

Please see attached estimate