



Over and Above Estimate

Region: 2

MATERIAL ETA 2-3 WEEK LEAD TIME

Location: NY023

CSS #: 34057

Maximo Work Order No. 15888

Asset#:

Date Issued: 1/12/2022

Original Description: Repair 10 Ton Crane on Main Floor of AMSA #12

Description of Repairs: Install new 8 button pendant assembly with cord and strain relief. Remove existing pendant station and wire in new. After completion of installation, will test for proper operation. **Please issue new WO for repair work needed upon approval.**

Non Pre-Priced Estimate:

Quantity	Line Item #	Description	Labor Hours	Unit	Labor	Materials	Equipment	Total
1		Materials (See attached estimate for line items)				\$605.00	\$0	\$605.00

Note: RS Means (Pre-Priced) not used in compiling this estimate.

Note: Subcontractor quote attached.

Estimate Summary:

Labor Hours	Labor Cost	Material Cost	Equipment Cost	Total Cost	CE Factor	Total Estimate
10 hours @145.00=\$1450.00	\$1450.00	\$605.00	750.00	\$2805.00	.90%	\$2524.50

Please see attached estimate

QUOTATION



Quote # 1-17IBA0TL
Version 1
Quote Date:
Jan 19, 2022

Customer Information

Customer	International Support Group LLC / US Army Reserve Center		
Location	200 Duane Rd Bayside		
Customer Contact	Tammy Lambdin 713-955-2599 tlambdin@internationalsupportgroup.com	Konecranes Contact	Wendy Bisazza (717) 517-1821 wendy.bisazza@konecranes.com
Offer Valid Until	Feb 18, 2022		

Assets

H-1

Single girder EOT - 1 trolley wire rope hoist, H-1, Truck shop

Business Location	US Army Reserve Center 200 Duane Rd Bayside	Service Request	1-94681938373
Contact	Michele Dubois 954-900-1095 mdubois@internationalsupportgroup.com	Inspection Date	Jan 18, 2022
		Technician	Anthony Valkosak

Risk Code	Description	Comments	USD
	Safety Risk 1-92380354455 Pushbutton pendant cable Other fault Install Product	Provide service technician and material to supply and install new 8-button pendant assembly w/cord and strain relief. Remove existing pendant station and wire in new. After installation complete, perform test for proper operation. Labor - 1 Man x 10 Hours x \$145.00/Hour - \$1,450.00 Material - Pendant Assembly w/Cord - \$605.00 Delivery - 2-3 Weeks Labor & Material Konecranes to Rent 26' Narrow Electric Scissors Lift - Included in Quote Tech Comment Please quote new three motion pendant with cable.	2,055.00

Currency	USD
Single girder EOT - 1 trolley wire rope hoist, H-1, Truck shop	2,055.00

International Support Group LLC / US Army Reserve Center

Name: _____

Date: _____

This quotation, proposal or offer is subject to and incorporates as if fully rewritten herein the Seller's Standard Terms and Conditions of Sale (Revision 06.01.2021), a copy of which is attached hereto or is available at www.konecranesUSA.com or upon request of Buyer.

For each Asset listed above, please indicate your acceptance of the corresponding quotation by taking any of the following actions: (a) placing your signature in the signature block immediately below the Asset indicated; (b) issuing a verbal or written purchase order, work order, or other similar order for the goods and/or services contemplated herein; or (c) giving verbal or written authorization to Konecranes to proceed with the performance of the services and/or delivery of the goods contemplated herein.

QUOTATION



Quote # 1-17IBA0TL
Version 1
Quote Date:
Jan 19, 2022

Currency	USD
Total for all assets	2,055.00
Equipment Rental	750.00
	2,805.00

Comments	
Travel	Travel, shipping & handling is included in quote. If quote is partially awarded, travel times are subject to change; fault lines under \$500 do not include travel time. Quote is based upon work being performed during normal Konecranes service hours, M-F, 7am - 4pm.
Equipment Rental	Konecranes to Rent 26' Narrow Scissors Lift - Included in Quote

This quotation, proposal or offer is subject to and incorporates as if fully rewritten herein the Seller's Standard Terms and Conditions of Sale (Revision 06.01.2021), a copy of which is attached hereto or is available at www.konecranesUSA.com or upon request of Buyer.

For each Asset listed above, please indicate your acceptance of the corresponding quotation by taking any of the following actions: (a) placing your signature in the signature block immediately below the Asset indicated; (b) issuing a verbal or written purchase order, work order, or other similar order for the goods and/or services contemplated herein; or (c) giving verbal or written authorization to Konecranes to proceed with the performance of the services and/or delivery of the goods contemplated herein.

SERVICE REPORT

Report Created: Jan 18, 2022 5:47 PM


Customer and Service Information

Customer	International Support Group LLC / US Army Reserve Center		
Business Location	US Army Reserve Center, Bayside, 200 Duane Rd		
City	Bayside		
Agreement			
Service Request	1-94681938373		
Description	PHI (NY) - SERVICE (per Quote 1-17HNIZV4) Provide service technician and 26' Narrow Scissors Lift to troubleshoot 10 Ton Sissco Crane which is having issues. (To be scheduled and completed on 1/18/2022)		
PO Number	CSS 34057		
Billing Type	Fixed		
Customer Contact	Michele Dubois 954-900-1095 mdubois@internationalsupportgroup.com	Konecranes Contact	Brett Kenna 6104273521 brett.kenna@konecranes.com

Component Condition

- ✓ Acceptable (No issues detected)
- ! Need Attention

Assets

 H-1 Single girder EOT - 1 trolley wire rope hoist			
Manufacturer	SISSCO	Span	70ft
Serial number	A2840-A	Lift	25ft
Criticality	High	Volt/Ph/Hz	460-3-60
Site Location	H-1 / Truck shop		
Capacity/SWL	10 tons		
Model	SGTRDM		
Service Products	Planned Repairs		

SERVICE REPORT

✓	Single girder EOT - 1 trolley wire rope hoist	Single girder EOT - 1 trolley wire rope hoist	Repaired
	Date Reported	Jan 18, 2022	
	Technician	Anthony Valkosak	
	Task Type	Repair	
	Fault Code	Other fault	
	Risk	Safety Risk	
	Recommendation	Repair	
	Comment:		
	Upon troubleshooting a electrical short was discovered in the hoist up motion ckt		
	Pendant cable was compromised and compromised section was removed		
	However it is to be noted pendant cable wiring is old and has twist in		
	The cord grip in the pendant is broken and a rudimentary repair was made to put crane into service for client		
	The repair does not compromise safety however forward looking reliability cannot be guaranteed for client		
	It is my recommendation that a new cable and pendant be installed as a proactive measure		
	Strain relief was repaired in addition to the wiring		
	All functions tested including hoist limits		
	Crane returned to service		
	Tony v		


Electrics

Control system

! Pushbutton pendant cable		Quote
Date Reported	Jan 18, 2022	
Technician	Anthony Valkosak	
Task Type	Change	
Fault Code	Other fault	
Risk	Safety Risk	
Recommendation	Install Product	
Comment:		
Please quote new three motion control ends t and cable for client		



Jan 18, 2022 12:16 PM Jody Trapp, Customer



Jan 18, 2022 12:08 PM Anthony Valkosak, Technician

Findings and Actions

Safety Risk **WARNING**

Indicates an unsafe condition. Failure to remedy such condition before continued operation of the identified Asset may result in personal injury including death, or property damage.

Production Risk

Indicates an inefficient condition. Failure to remedy such condition before continued operation of the identified asset may result in inefficient asset performance or an interruption in production.

Undetermined Condition

Indicates that the condition could not be directly verified through visual inspection as a result of asset configuration and/or obstruction.

The condition of certain components cannot be directly verified through visual inspection without further disassembly and/or the use of other inspection methods. These advanced services are generally excluded from the scope of typical compliance and preventive maintenance inspections. Consultation Services may be added to a Service Program or offered on a stand-alone basis to assess the condition of these components. Inspection frequency for these components should follow OEM recommendations and/or governing regulations. If no records are available, we recommend appropriate inspections be carried out to determine current condition and to establish a baseline for recurring inspections.

Improvement Opportunity

Indicates a potential opportunity to improve the safety, productivity, application or useful life of the asset.

Acceptable / Repaired Item

Component condition is verified by Konecranes service technician. No actions required. If a component or other object has been repaired within the service visit, green color code is shown as well.

KONECRANES' STORE
SPARE PARTS, ACCESSORIES AND SELECT
PRE-CONFIGURED LIFTING EQUIPMENT
store.konecranes.com

ONLINE
ANY TIME

YOUR KONECRANES
CRANE MAINTENANCE INFORMATION
AND REMOTE MONITORING DATA
your.konecranes.com