

Additional Funding Request

Site: NY023	WO# 34184 CSS # 16284
Description of Repairs	Fan Coils are not working, Trouble shoot , adjust manually to override, since BMS System is not working. Install 3 Relays
Diagnosis: Initial Work Order	Repair Fan coil control system. System controls are not calling for heat in some zones.
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	<u>8hrs@235.00</u> = \$1880.00
Additional Material Cost to Perform Repairs	75.00
Total Cost of Repair	\$1955.00

ACAV SERVICES

January 26, 2022



ESTIMATE 012622 CSS34184 WO1284

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 206)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	<p>NY023 BLDG 206</p> <p>FAN COIL UNITS NOT WORKING</p> <p>TROUBLE SHOOT SYSTEM AND ADJUST MANUALLY SINCE THE BMS SYSTEM IS NOT WORKING</p> <p><u>MATERIAL</u></p> <p>3EA RELAYS</p> <p><u>LABOR</u></p> <p>8 HRS @ \$235.00</p> <p>2 MEN 4 HRS EA</p> <p>TOTAL</p>		\$75.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581