

Additional Funding Request

Site: NY023	WO# 16628 CSS #34688
Description of Repairs	Remove gate and replace drive Wheel Assembly and drive wheel track. Rehang Gate and check for proper operation
Diagnosis: Initial Work Order	Repair MEP lot gate. Retaining spring gear wheel.
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	X2 men @ 8 Hours total @225.00 HR= \$1800.00
Additional Material Cost to Perform Repairs	\$685.00
Total Cost of Repair	\$2485.00

ACAV SERVICES

February 25, 2022



ESTIMATE 022522 CSS34688 WO16628

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (MEP LOT)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	<p>NY023 MEP LOT</p> <p>REPAIR MEP LOT GATE</p> <p>REMOVE GATE AND REPLACE</p> <p>DRIVE WHEEL ASSEMBLY AND</p> <p>DRIVE WHEEL TRACK</p> <p>REHANG GATE AND CHECK</p> <p>OPERATION</p> <p><u>MATERIAL</u></p> <p>DRIVE WHEEL ASSEMBLY AND</p> <p>DRIVE WHEEL TRACK</p> <p><u>LABOR</u></p> <p>8 HRS @ \$225.00</p> <p>2 MEN 4 HRS EACH</p> <p><u>TOTAL</u></p>		<p>\$685.00</p> <p>\$1800.00</p> <p>\$2485.00</p>

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581