

Additional Funding Request

Site: NY023	WO# 19758 CSS # 90570
Description of Repairs	The fresh air ventilation system is not working, and further diagnostic increase is requested. A complete diagnostic of the entire system, including all electrical and mechanical components, to develop an accurate scope of work for the repair of the system.
Diagnosis: Initial Work Order	building 121 repair ventilators
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	9 hours @ 250.00 (x2 men) = \$2250.00
Additional Material Cost to Perform Repairs	
Total Cost of Repair	\$2250.00

ACAV SERVICES

November 11, 2022



ESTIMATE 111122 CSS90570 WO19758

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 121)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		<p>NY23 (BLDG 121 OMS) FLUID STORAGE AREA LOCATED ON THE EAST END OF THE BUILDING</p> <p>FRESH AIR VENTILATION SYSTEM IS NOT WORKING</p> <p>A COMPLETE DIAGNOSTIC HAS TO CONDUCTED OF THE ENTIRE SYSTEM TO INCLUDE ALL ELECTRICAL AND MECHANICAL COMPONENTS IN ORDER TO DEVELOP AN ACCURATE SOW FOR THE REPAIR OF THIS SYSTEM</p>		

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		<p>THIS REPAIR IS COMPLICATED SINCE NO GOVERNMENT PERSONNEL ON SITE HAVE ANY INFORMATION ON THE OPERATION OF THE SYSTEM AND WHAT COMPONENT IS DEFECTIVE</p> <p><u>LABOR</u></p> <p>9 HRS @ \$250.00</p> <p>(2 MEN 4.5 HRS EA)</p>		
		TOTAL		\$2250.00
				TOTAL \$2250.00

