

Over and Above Estimate

Region: 2

Revised CE

Location: NY023

CSS # 90601

Maximo Work Order No. 19764

Asset#:

Date Issued: 11/01/2022

Original Description: diagnose and repair man doors and bay door building 118

Description of Repairs: 1. Lubricate hardware, Repair closer, possible new hinge(s), new sweep
2. Lubricate hardware, new sweep exterior of door
3. Lubricate hardware, remove sill/re-concrete/new anchors, new sweep exterior of door, grind damage in frame
4. Lubricate hardware, remove sill/re-concrete/new anchors, new sweep exterior of door, re-ta top hinge

5. Lubricate hardware, remove sill/re-concrete/new anchors, new sweep exterior of door, grind down bump/hole on frame and fill with j-b weld
6. Lubricate hardware, remove sill/re-concrete/new anchors, new sweep exterior of door, sand/grind rust and paint door inside and out

Overhead door

1. Replace switches
2. Replace bracket
3. Lubricate and adjust chain and linkage

Non-Pre-Priced Estimate:

Quantity	Line Item #	Description	Labor Hours	Unit	Labor	Materials	Equipment	Total
1		Materials (See attached estimate for line items)				\$865.00		

Note: RS Means (Pre-Priced) is not used in compiling this estimate.

Note: Subcontractor quote attached.

Estimate Summary:

Labor Hours	Labor Cost	Equipment	Material	Total Cost	CE Factor	Total Estimate
22 hours @ 250.00 = 5500.00	\$5500.00		865.00	\$6365.00	1.02	\$6492.30

ACAV SERVICES

November 29, 2022



ESTIMATE 111622 CSS90601 WO19764

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 118)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		NY23 (BLDG 118)		
		REPAIR OVERHEAD DOOR (1EA)		
		REPAIR MAN DOOR (6EA)		
		1. Lubricate hardware, Repair closer, possible new hinge(s), new sweep		
		2. Lubricate hardware, new sweep exterior of door		
		3. Lubricate hardware, remove sill/re-concrete/new anchors, new sweep exterior of door, grind damage in frame		
		4. Lubricate hardware, remove sill/re-concrete/new anchors, new sweep exterior of door, re-tap top hinge		

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

