

Additional Funding Request

Site: NY023-118	WO# 19768 CSS #90628
Description of Repairs	Remove door and replace the upper hinge, rehang door and adjust for proper operation
Diagnosis: Initial Work Order	building 128 interior doors need adjustment do not work properly
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	3 hrs @ 225.00= 675.00 Repair Labor
Additional Material Cost to Perform Repairs	18.00
Total Cost of Repair	693.00

ACAV SERVICES

November 4, 2022

Corrected CSS 90628
Corrected WO 19768



ESTIMATE 110422 CSS90601 WO19764

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 128)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		NY23 (BLDG 128) BROKEN DOOR 2ND FLOOR DPW OFFICE REMOVE DOOR AND REPLACE UPPER HINGE REHANG DOOR AND ADJUST <u>MATERIAL</u> 1EA HEAVY DUTY STEEL HINGE		
		<u>LABOR</u> 3 HRS @ \$225.00		\$18.00 \$675.00
		TOTAL		\$693.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

202

