

Additional Funding Request

Site: NY023	WO# 19784 CSS # 90729
Description of Repairs	Install window guards on men's second floor latrine area
Diagnosis: Initial Work Order	safety bars 128 men's room window guard
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	2 hrs @250.00= 500.00
Additional Material Cost to Perform Repairs	125.00
Total Cost of Repair	\$625.00

ACAV SERVICES

November 16, 2022



ESTIMATE 111622 CSS90729 WO19784

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 128)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		NY23 (BLDG 128) MENS 2ND FLOOR LATRINE		
		INSTALL WINDOW GUARDS		
		<u>MATERIAL</u>		
		1EA ADJUSTABLE WINDOW GUARD KIT		\$125.00
		<u>LABOR</u>		
		2 HRS @ \$250.00		\$500.00
		TOTAL		\$625.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

