

### Over and Above Estimate

**Region:** 2

**Location:** NY023

**CSS # 90935**

**Maximo Work Order No. 20193**      **Asset#:**

**Date Issued:** 11/28/2022

**Original Description:** Fix or replace overhead door coil in AMSA 12 Building #123

**Description of Repairs:** Replace overhead door safety coil, lubricate tracks and repair guide wheels

#### Non-Pre-Priced Estimate:

Quantity	Line Item #	Description	Labor Hours	Unit	Labor	Materials	Equipment	Total
1		Materials (See attached estimate for line items)				\$980.00		

*Note: RS Means (Pre-Priced) is not used in compiling this estimate.*

*Note: Subcontractor quote attached.*

#### Estimate Summary:

Labor Hours	Labor Cost	Equipment	Material	Total Cost	CE Factor	Total Estimate
X2 men at 4hours each at 250.00 per hour= 2000.00	\$2000.00		\$980.00	\$2980.00	1.02	\$3039.60

**Please see the attached estimate.**

# ACAV SERVICES

December 12, 2022



ESTIMATE 121222 CSS90935 WO20193

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 123)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		<p><b>NY23 (BLDG 123) (AMSA WEST DOOR)</b></p> <p><b>REPLACE OVERHEAD DOOR SAFETY COIL</b></p> <p><b>LUBRICATE TRACKS</b></p> <p><b>REPAIR GUIDE WHEELS</b></p> <p><b><u>MATERIAL</u></b></p> <p><b>OVERHEAD DOOR SAFETY COIL</b></p> <p><b>POWER SUPPLY LINE</b></p> <p><b>GUIDE WHEELS</b></p>		\$980.00

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		<b><u>LABOR</u></b> <b>8 HRS @ \$250.00</b> <b>2 MEN 4 HRS EA</b>		<b>\$2000.00</b>
		<b>TOTAL</b>		<b>\$2980.00</b>

\$

**TOTAL \$2980.00**

