

## Additional Funding Request

<b>Site: NY023</b>	<b>WO#20603 CSS # 91379</b>
Description of Repairs	Repair gate to MEP hit by a vehicle. Remove the damaged guide rail and install a new rail. Adjust rollers, align new guide rail and lubricate system
Diagnosis: Initial Work Order	MEP main gate fix tensioner gate stuck in open position
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	1250.00
Additional Material Cost to Perform Repairs	375.00
Total Cost of Repair	\$1625.00

# ACAV SERVICES

January 9, 2023



ESTIMATE 010923 CSS91379 WO20603

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (MEP LOT)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		<p><b>NY23 (MEP LOT)</b></p> <p><b>REPAIR GATE TO MEP LOT (HIT BY VEHICLE)</b></p> <p><b>REMOVE DAMAGED GUIDE RAIL AND INSTALL NEW RAIL</b></p> <p><b>ADJUST ROLLERS ALIGN NEW GUIDE RAIL AND LUBRICATE SYSTEM</b></p> <p><b><u>MATERIAL</u></b></p> <p><b>1EA 20'X21 1/2"X4" ALUMINUM GUIDE RAIL</b></p>		\$375.00

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		<b>LABOR</b> <b>5 HRS @ \$250.00</b> <b>(INCLUDES 2HR DIAGNOSTIC FEE)</b>		<b>\$1250.00</b>
		<b>TOTAL</b>		<b>\$1625.00</b>

\$

**TOTAL \$1625.00**

