

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 20618 CSS # 91490</b>
Description of Repairs	Install 2ea 3x5 HD wire mesh security guards on the outside of the windows.
Diagnosis: Initial Work Order	Building 128 install window bars ID office windows for physical security requirement..2-windows
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	1500.00
Additional Material Cost to Perform Repairs	625.00
Total Cost of Repair	2125.00

# ACAV SERVICES

January 18, 2023



ESTIMATE 011823 CSS91490 WO20618

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 128)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		<p><b>NY23 (BLDG 128 ID SECTION)</b></p> <p><b>INSTALL 2EA 3X5 HD WIRE MESH SECURITY GUARDS ON THE OUTSIDE OF THE WINDOWS</b></p> <p><b><u>MATERIAL</u></b></p> <p><b>2EA 3X5 HD WIRE MESH SECURITY GUARDS (\$275.00 EA)</b></p> <p><b>MOUNTING HARDWARE</b></p> <p><b>TOTAL MATERIAL</b></p> <p><b><u>LABOR</u></b></p> <p><b>6 HRS @ \$250.00</b></p> <p><b>TOTAL</b></p>		

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581

