

Additional Funding Request

| | |
|---|--|
| Site: NY023 | WO#21451 CSS # 92236 |
| Description of Repairs | Main gate is not operating properly. Will need to remove the gate, replace 2ea hinges, replace bolts and nuts. |
| Diagnosis: Initial Work Order | MEP man gate out of alignment doesn't close |
| Explanation of Additional Costs for Repairs | |
| Additional Labor Cost to Perform Repairs | 900.00 |
| Additional Material Cost to Perform Repairs | 75.00 |
| Total Cost of Repair | \$975.00 |
| | |
| | |

ACAV SERVICES

February 23, 2023



ESTIMATE 021922 CSS92236 WO21451

| Bill To | | Ship To | |
|---------------|---|-----------------|--|
| Customer | International Support Group M DUBOIS, | Recipient | 99 RSC RD DPW L CORBO |
| Customer ID# | NY023 (MEP GATE) | Address | Ernie Pyle USARC BLDG 206 Ft Totten NY |
| Address | 9050 Pines Blvd STE 150 Pembroke Pines FL 33024 | Phone | 718 631 6188 |
| Phone | 954 900 1095 | | |
| Payment Due | NET 30 | Delivery Date | N/A |
| Salesperson | JW | Shipping Method | N/A |
| Payment Terms | N/A | Shipping Terms | N/A |

| Qty. | Item# | Description | Unit Price | Line Total |
|------|-------|--|------------|-----------------|
| | | NY23 (MEP GATE) FRONT DOOR MAN GATE NOT OPERATING PROPERLY REMOVE GATE REPLACE 2EA HINGES REPLACE BOLTS AND NUTS USING LOCK TIGHT <u>MATERIAL</u> HINGES, BOLTS MISC HARDWARE | | \$75.00 |
| | | <u>LABOR</u> 6 HRS @ \$150.00 (2 MEN 3 HRS EACH) | | \$900.00 |
| | | TOTAL | | \$975.00 |

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581



