

### Over and Above Estimate

**Region:** 2

**Location:** NY023-128

**CSS #:** 92835

**Maximo Work Order No.** 21747

**Asset#:**

**Date Issued:** 03/27/2023

**Original Description:** Building 128 boiler discovered this morning broken down

**Description of Repairs:** Repair broken steam pipe in crawl space.

#### Non Pre-Priced Estimate:

Quantity	Line Item #	Description	Labor Hours	Unit	Labor	Materials	Equipment	Total
1		Materials (See attached estimate for line items)				\$890.00	\$	\$890.00

*Note: RS Means (Pre-Priced) not used in compiling this estimate.*

*Note: Subcontractor quote attached.*

#### Estimate Summary:

Labor Hours	Labor Cost	Material	Equipment Cost	Total Cost	CE Factor	Total Estimate
<a href="#">12 hr@250.00=</a> 3000.00	\$3000.00	\$890.00	\$	\$3890.00	1.02	\$3967.80

**Please see attached estimate**

# ACAV SERVICES

April 4, 2023



## ESTIMATE 040323 CSS92835 WO21747

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 128)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		<b>NY23 (BLDG 128)</b>  <b>BOILER #1 NOT WORKING BROKEN STEAM PIPE DISCOVERED IN CRAWL SPACE</b>  <b><u>MATERIAL</u></b> <b>20FT 1IN COOPER PIPE</b> <b>2EA 1IN UNIONS</b> <b>2EA 1IN COPPER/STEEL UNIONS</b> <b>2EA 1IN PIPE NIPPLES</b> <b>2EA 1IN MALE ADAPTERS</b> <b>2EA 1IN COUPLINGS</b>		

### ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		<b>TOTAL MATERIAL</b>		<b>\$890.00</b>
		<b><u>LABOR</u></b>		
		<b>12 HRS @ 250.00 PER HR</b>		
		<b>(2 MEN 6HRS EA)</b>		
		<b>TOTAL</b>		<b>\$3000.00</b>
		<b>TOTAL</b>		<b>\$3890.00</b>
			<b>TOTAL</b>	<b>\$3890.00</b>

