

## Additional Funding Request

<b>Site: NY023</b>	<b>WO# 21768 CSS #93039</b>
Description of Repairs	Remove drive motor and replace control bearings and make adjustments
Diagnosis: Initial Work Order	MEP gate stuck in open position physical security issue
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	450.00
Additional Material Cost to Perform Repairs	115.00
Total Cost of Repair	\$565.00

# ACAV SERVICES

April 17, 2023



ESTIMATE 041723 CSS93039 WO21768

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (MEP LOT)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		<p><b>NY23 (MEP LOT)</b></p> <p><b>ENTRANCE GATE STUCK IN OPEN POSITION</b></p> <p><b>REMOVE DRIVE MOTOR AND REPLACE CONTROL BEARINGS AND ADJUST</b></p> <p><b><u>MATERIAL</u></b></p> <p><b>1EA SET OF DRIVE BEARINGS</b></p> <p><b><u>LABOR</u></b></p> <p><b>2 HRS @ 225.00 PER HR</b></p> <p><b>TOTAL</b></p>		

**TOTAL \$565.00**

## ACAV Services

11 Snug Cove Lane  
Bayville NY 11709  
Jacka377@verizon.net  
516 941 6581

