

Additional Funding Request

Site: NY023	WO# 17664 CSS # 931
Description of Repairs	Replace broken 6" extreme lower roller wheel adjust/realign track on entire gate.
Diagnosis: Initial Work Order	Repair upper parking lot gate at the third floor of building #200
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	<u>8hrs@235.00</u> = \$1880.00
Additional Material Cost to Perform Repairs	175.00
Total Cost of Repair	\$2055.00

ACAV SERVICES

June 11, 2022



ESTIMATE 060922 CSS931 WO17654

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 200)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
1	1	<p>NY23 BLDG 200 UPPER PARKING LOT GATE</p> <p>REPLACE BROKEN 6" "EXTREME" LOWER ROLLER WHEEL, ADJUST/REALIGN TRACK AND ENTIRE DATE</p> <p><u>MATERIAL</u></p> <p>1 EA 6" "EXTREME" LOWER ROLLER WHEEL</p> <p><u>LABOR</u></p> <p>8 HRS @ \$235.00 PER HOUR (2 MEN 4 HRS EACH)</p> <p><u>TOTAL</u></p>		

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581



