

Additional Funding Request

Site: NY023	WO# 22125 CSS #93286
Description of Repairs	Repair 4 large holes in caging created during pipe removal during FFR. Frame out area and install caging to secure vault (No pictures taken due to security protocol)
Diagnosis: Initial Work Order	Building 200 large arms vaults...repair 4-holes left after pipes were removed during FFR work.
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	1400.00
Additional Material Cost to Perform Repairs	375.00
Total Cost of Repair	1775.00

ACAV SERVICES

May 6, 2023



ESTIMATE 050623 CSS93286 WO22125

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 200)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/A
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		<p>NY23 (BLDG 200) ARMS ROOM</p> <p>SECURE AREA NO PHOTOS</p> <p>AUTHORIZED</p> <p>REPAIR 4 LARGE HOLES IN THE</p> <p>CAGING CREATED DURING PIPE</p> <p>REMOVAL FOR THE FFR</p> <p>FRAME OUT THE AREA AND</p> <p>INSTALL CAGING TO SECURE</p> <p>VAULT (CUT TO SIZE)</p> <p><u>MATERIAL</u></p> <p>CAGING</p> <p>MISC NUT AND BOLTS</p>		\$375.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		<u>LABOR</u> 8 HRS @ \$175.00 PER HR		\$1400.00
		TOTAL		\$1775.00
TOTAL \$1775.00				