

SERVICE REPORT

KONECRANES®
Lifting Businesses™

Report Created: Jul 11, 2023 6:35 AM

Customer and Service Information

Customer	International Support Group LLC / US Army Reserve Center		
Business Location	US Army Reserve Center, Bayside, 200 Duane Rd		
City	Bayside		
Agreement			
Service Request	1-99083770702		
Description	PHI (NY) - SERVICE CALL / REPAIR Provide service technician and scissors lift to perform Service Call on 10 Ton Sisco Crane w/Yale Hoist to determine issue of "Jumped Guide" on Asset #H-1 per Quote# 1-19I63MAA.		
PO Number	Email Approval		
Billing Type	Fixed		
Customer Contact	Michele Dubois 954-900-1095 mdubois@internationalsupportgroup.com	Konecranes Contact	Brett Kenna 6104273521 brett.kenna@konecranes.com

Component Condition

✓ Acceptable (No issues detected)

! Need Attention

Assets

 H-1 Single girder EOT - 1 trolley wire rope hoist	Manufacturer SISSCO	Span 70ft		
Serial number A2840-A	Lift 25ft			
Criticality High	Volt/Ph/Hz 460-3-60			
Site Location H-1 / Truck shop				
Capacity/SWL 10 tons				
Model SGTRDM				
Service Products Planned Repairs				
Hoists				
Asset Description	Serial number	Model Type	Manufacturer	Capacity
	CK5835XC	EEW10-23PT19D4	YALE	10 t

Trolley

Hoisting machinery
CK5835XC, YALE, EEW10-23PT19D4, 10 t

! Rope guide

Quote

Date Reported Jul 10, 2023
Technician Tony Farquharson
Task Type Operational assessment
Fault Code Acceptable
Risk **Improvement Opportunity**
Recommendation No Action

Comment:

I would recommend installing a rope guide or a retrofit rope guide prevent Hoists from skipping grooves when the rope goes slack.

! Hoisting wire rope Measure 9.51 mm wire rope diameter

Quote

Date Reported Jul 10, 2023
Technician Tony Farquharson
Task Type Operational assessment
Fault Code Cross wrapped on rope drum
Risk **Safety Risk**
Recommendation Replace

Comment:

Wire rope is wedged and wrapped around the drum a couple time at the motor side. Which causes the rope to jump two upper sheaves and kinked wire rope in multiple sections. I recommend replace wire rope and this crane needs to lockout from any further used for safety reasons.



Jul 10, 2023 2:56 PM Patrick Murray, Customer



Jul 10, 2023 8:41 PM Tony Farquharson, Technician

Findings and Actions

Safety Risk **WARNING**

Indicates an unsafe condition. Failure to remedy such condition before continued operation of the identified Asset may result in personal injury including death, or property damage.

Production Risk

Indicates an inefficient condition. Failure to remedy such condition before continued operation of the identified asset may result in inefficient asset performance or an interruption in production.

Undetermined Condition

Indicates that the condition could not be directly verified through visual inspection as a result of asset configuration and/or obstruction.

The condition of certain components cannot be directly verified through visual inspection without further disassembly and/or the use of other inspection methods. These advanced services are generally excluded from the scope of typical compliance and preventive maintenance inspections. Consultation Services may be added to a Service Program or offered on a stand-alone basis to assess the condition of these components. Inspection frequency for these components should follow OEM recommendations and/or governing regulations. If no records are available, we recommend appropriate inspections be carried out to determine current condition and to establish a baseline for recurring inspections.

Improvement Opportunity

Indicates a potential opportunity to improve the safety, productivity, application or useful life of the asset.

Acceptable / Repaired Item

Component condition is verified by Konecranes service technician. No actions required. If a component or other object has been repaired within the service visit, green color code is shown as well.

KONECRANES® STORE

SPARE PARTS, ACCESSORIES AND SELECT
PRE-CONFIGURED LIFTING EQUIPMENT

store.konecranes.com

ONLINE
ANY TIME

YOURKONECRANES

CRANE MAINTENANCE INFORMATION
AND REMOTE MONITORING DATA

your.konecranes.com

SAFETY NOTIFICATION

KONECRANES®
Lifting Businesses™

Report Created: Jul 11, 2023 6:35 AM

Customer and Service Information

Customer	International Support Group LLC / US Army Reserve Center		
Business Location	US Army Reserve Center, Bayside, 200 Duane Rd		
City	Bayside		
Agreement			
Service Request	1-99083770702		
Description	PHI (NY) - SERVICE CALL / REPAIR Provide service technician and scissors lift to perform Service Call on 10 Ton Sissco Crane w/Yale Hoist to determine issue of "Jumped Guide" on Asset #H-1 per Quote# 1-19I63MAA.		
PO Number	Email Approval		
Billing Type	Fixed		
Customer Contact	Michele Dubois 954-900-1095 mdubois@internationalsupportgroup.com	Konecranes Contact	Brett Kenna 6104273521 brett.kenna@konecranes.com

Component Condition

✓ Acceptable (No issues detected)

! Need Attention

Assets

 H-1 Single girder EOT - 1 trolley wire rope hoist	Manufacturer SISSCO	Span 70ft		
Serial number A2840-A	Lift 25ft			
Criticality High	Volt/Ph/Hz 460-3-60			
Site Location H-1 / Truck shop				
Capacity/SWL 10 tons				
Model SGTRDM				
Service Products	Planned Repairs			
Hoists				
Asset Description	Serial number	Model Type	Manufacturer	Capacity
	CK5835XC	EEW10-23PT19D4	YALE	10 t

Trolley

Hoisting machinery
CK5835XC, YALE, EEW10-23PT19D4, 10 t

SAFETY NOTIFICATION

KONECRANES®
Lifting Businesses™

! Hoisting wire rope Measure 9.51 mm wire rope diameter

Quote

Date Reported

Jul 10, 2023

Technician

Tony Farquharson

Task Type

Operational assessment

Fault Code

Cross wrapped on rope drum

Risk

Safety Risk

Recommendation

Replace

Comment:

Wire rope is wedged and wrapped around the drum a couple time at the motor side. Which causes the rope to jump two upper sheaves and kinked wire rope in multiple sections. I recommend replace wire rope and this crane needs to lockout from any further used for safety reasons.



Jul 10, 2023 2:56 PM Patrick Murray, Customer



Jul 10, 2023 8:41 PM Tony Farquharson, Technician

Findings and Actions

Safety Risk  **WARNING**

Indicates an unsafe condition. Failure to remedy such condition before continued operation of the identified Asset may result in personal injury including death, or property damage.

Acceptable / Repaired Item

Component condition is verified by Konecranes service technician. No actions required. If a component or other object has been repaired within the service visit, green color code is shown as well.

KONECRANES® STORE

SPARE PARTS, ACCESSORIES AND SELECT
PRE-CONFIGURED LIFTING EQUIPMENT

store.konecranes.com

**ONLINE
ANY TIME**

YOURKONECRANES

CRANE MAINTENANCE INFORMATION
AND REMOTE MONITORING DATA

your.konecranes.com







