

Additional Funding Request

Site:	WO #23319 CSS #93787
Description of Repairs	Repair short in pump #1; Power wash coils; bleed system; add 4lbs of Freon; check building fan coil unit
Diagnosis: Initial Work Order	Trouble shoot A/C system in building 206. chiller operates spatially and a number of fan coil units do not work efficiently
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	1600.00
Additional Material Cost to Perform Repairs	390.00
Total Cost of Repair	1990.00

ACAV SERVICES

June 15, 2023



ESTIMATE 061623 CSS93787 WO23319
PO100041043

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 206)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		<p>NY23 (BLDG 206)</p> <p>DIAGNOSE PROBLEM WITH CHILLER, OPERATES SPORADICALLY</p> <p>#1 PUMP NOT WORKING (SHORT IN THE SWITCH)</p> <p>POWER WASH COILS</p> <p>ADD FREON 4LBS</p> <p>BLEED SYSTEM</p> <p>CHECK BUILDING FAN COIL UNITS</p>		

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

Qty.	Item#	Description	Unit Price	Line Total
		<u>MATERIAL</u> 4LBS OF R410A FREON		\$390.00
		<u>LABOR</u> 8 HRS @ \$200.00 2 MEN 4 HRS EA		\$1600.00
		TOTAL		\$1990.00
TOTAL \$1990.00				

WARNING LABEL

WARNING: RISK OF ELECTRICAL SHOCK
CAN CAUSE SEVERE INJURY OR DEATH.
DO NOT USE POWER SOURCE
UNLESS EQUIPMENT IS PROPERLY
GROUNDED.

Carrier

DO NOT FORK

DO NOT FORK