

Additional Funding Request

Site:	WO #22728 CSS #93910
Description of Repairs	Toilet leaking; Flushometer leaking and has to be rebuilt
Diagnosis: Initial Work Order	Repair leak in 3rd Floor toilet in Building #206, water puddling on the floor
Explanation of Additional Costs for Repairs	1 Hour Incurred diagnostic cost
Additional Labor Cost to Perform Repairs	600.00
Additional Material Cost to Perform Repairs	50.00
Total Cost of Repair	650.00

ACAV SERVICES

June 14, 2023



ESTIMATE 061323 CSS93910 WO22728
PO100041044

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RSC RD DPW L CORBO
Customer ID#	NY023 (BLDG 206)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	16 MAR 2023
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty.	Item#	Description	Unit Price	Line Total
		<p>NY23 (BLDG 206) 3RD FLOOR LATRINE</p> <p>TOILET LEAKING</p> <p>FLUSHOMETER LEAKING AND HAS TO BE REBUILT</p> <p><u>MATERIAL</u></p> <p>1EA SLOAN MODEL R10004A FLUSHOMETER REBUILT KIT</p> <p><u>LABOR</u></p> <p>2 HRS @ \$200.00</p> <p>1 HR DIAGNOSTIC FEE @200.00</p> <p><u>TOTAL</u></p>		

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

