

Additional Funding Request

Site: NY058	WO# 3396	CSS # 15647	Asset# NA
Description of Repairs	Replace defective lighting control unit		
Diagnosis: Initial Work Order CSS# 15647	All lights out in mens locker room		
Explanation of Additional Costs for Repairs	Labor and material to replace defective lighting control unit		
Additional Labor Cost to Perform Repairs	\$330.00		
Additional Material Cost to Perform Repairs	143.72		
Total Cost of Repair	\$473.72		

MSL Electric, LLC

6555 GRAND AVE
NY 11378

Estimate

Date	Estimate #
6/25/2019	1148

Name / Address
International Support Group 9050 Pine Blvd., Suite 150 Pembroke Pines, FL 33024

				Project
Description	Qty	Rate	Total	
Removal and replacement of defective lighting control unit for the Men's Locker Room WO#2-3396, CSS#15647 CW2 Kerry P. Hein Center, Shoreham, NY. Electrical & Lighting Control Unit CU300A, Wire nuts and misculaneous.	3	110.00	330.00	
	1	132.00	132.00T	
				Subtotal \$462.00
				Sales Tax (8.875%) \$11.72
				Total \$473.72

