

Additional Funding Request

Site: NY058	WO# 18265 CSS # 1640
Description of Repairs	Solid Oak Door leading to drill hall. Remove and repair with new hinges if needed and rehang. ACAV is scheduled for Boiler PM why requesting quick approval to reduce in charges.
Diagnosis: Initial Work Order	Change hinge on drill hall door
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	8hrs@225.00 <u>hr</u> = \$1800.00
Additional Material Cost to Perform Repairs	
Total Cost of Repair	\$1800.00

ACAV SERVICES

July 21, 2022



ESTIMATE 072133 CSS1640 WO18265

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RD DPW
Customer ID#	NY058 (MAIN BLDG)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	25 May 22
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty	Item #	Description	Unit Price	Line Total
1	1	<p>NY058 MAIN BLDG</p> <p>SOLID OAK DOOR LEADING TO THE DRILL FLOOR NEEDS REPAIR REMOVE AND REHANG DOOR</p> <p>LABOR</p> <p>8 HRS @ \$225.00 PER HOUR</p> <p>TOTAL</p> <p>NOTE WORK MUST BE APPROVED NLT 12 AUG TO BE ABLE TO HONOR THIS PRICE</p>		\$1800.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581







