

Additional Funding Request

Site: NY058	WO# 17192 CSS 165
Description of Repairs	Remove main gate. Install a lower 20ft guide rail with 2ea 8' guide wheels. Rehang gate and adjust alignment.
Diagnosis: Initial Work Order	Main gate of facility needs adjustment
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	10 total man hours @ 155.00 hr = \$1550.00
Additional Material Cost to Perform Repairs	\$475.00
Total Cost of Repair	\$2025.00
	Existing gate was designed with no wheels, the drag of the gate is what is causing the gate malfunction. The fabrication of the guide wheels is necessary to modify the design to install wheels.

ACAV SERVICES

May 10, 2022



ESTIMATE 051022 CSS165 WO17192

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RD DPW
Customer ID#	NY058 (MAIN BLDG)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	N/a
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty	Item #	Description	Unit Price	Line Total
1	1	NY058 MAIN BLDG (FRONT GATE) MAIN GATE DRAGGING REMOVE MAIN GATE INSTALL A LOWER 20FT GUIDE RAIL WITH 2EA 8' GUIDE WHEELS REHANG GATE AND ADJUST ALIGNMENT <u>MATERIAL</u> 20FT ALUMINUM GUIDE RAIL 2EA CUSTOM FABRICATED 8" HEAVY DUTY GUIDE WHEELS HANGERS AND HARDWARE		\$475.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581

Qty	Item #	Description	Unit Price	Line Total
		<u>LABOR</u>		
		10 HRS @ \$155.00 PER HOUR		\$1550.00
		TOTAL		\$2025.00
<p>Existing gate was designed with no wheels, the drag of the gate is what is causing the gate malfunction. The fabrication of the guide wheels is necessary to modify the design to install wheels.</p>				
TOTAL				\$2025.00