

Additional Funding Request

Site: NY058	WO# 18690 CSS # 1856
Description of Repairs	Upon arrival on site determined unit needs further diagnostic and check of system and connection to BMS System that has been down for several years.
Diagnosis: Initial Work Order	Troubleshoot/ Diagnose AC on 2nd floor of Training building
Explanation of Additional Costs for Repairs	
Additional Labor Cost to Perform Repairs	8hrs@235.00 <u>hr</u> = \$2000
Additional Material Cost to Perform Repairs	
Total Cost of Repair	\$1880.00

ACAV SERVICES

July 27, 2022



ESTIMATE 072522 CSS1856

Bill To		Ship To	
Customer	International Support Group M DUBOIS,	Recipient	99 RD DPW
Customer ID#	NY058 (MAIN BLDG)	Address	Ernie Pyle USARC BLDG 206 Ft Totten NY
Address	9050 Pines Blvd STE 150 Pembroke Pines FL 33024	Phone	718 631 6188
Phone	954 900 1095		
Payment Due	NET 30	Delivery Date	25 May 22
Salesperson	JW	Shipping Method	N/A
Payment Terms	N/A	Shipping Terms	N/A

Qty	Item #	Description	Unit Price	Line Total
1	1	NY058 MAIN BLDG 2ND FLOOR AC NOT WORKING DIAGNOSE AND CHECK AC SYSTEM AND BMS <u>LABOR</u> 8 HRS @ \$235.00 PER HOUR TOTAL		\$1880.00

ACAV Services

11 Snug Cove Lane
Bayville NY 11709
Jacka377@verizon.net
516 941 6581



McQuay
Air Conditioning

