

Additional Funding Request

Site: NY058	WO# 6505	CSS # 23185	Asset# NA
Description of Repairs	Repair: Install new 1.5 HP Fan motor and repair all loose wiring, will include new capacitor Model number is PFH027A-PL7 serial number is 1031N201491		
Diagnosis: Initial Work Order CSS# 23185	unit has no motor and has loose wires appears as if was in process of being replaced and never completed.		
Explanation of Additional Costs for Repairs			
Additional Labor Cost to Perform Repairs	4 x \$85.00= \$340.00		
Additional Material Cost to Perform Repairs	\$384.00		
Total Cost of Repair	\$724.00		

ISG IN HOUSE AFR

CSS #: Work Order #:
 Emergency Urgent Routine

Company Name:	International Support Group	Facility ID:	NY058
Contractor POC:	Michele Dubois		
Telephone No:	1-954-900-1095 x 1006	Building/Location; (e.g.,	
E-Mail Address:	mdubois@internationalsupportgr	Classroom/Room #)	
Assigned Technician(s):	Deen		

DESCRIPTION of WORK and EXPLANATION for REPAIRS or REPLACEMENT

Diagnostic: unit has no motor and has loose wires appears as if was in process of being replaced and never completed.

Repair: Install new 1.5 HP Fan motor and repair all loose wiring, will include new capacitor Model number is PFH027A-PL7 serial number is 1031N201491

LABOR/MATERIAL		QUANTITY	MATERIAL/ SUB UNIT DOLLAR AMOUNT	LBR/HR \$115.00	LINE ITEM TOTAL DOLLAR AMOUNT
Fan motor - \$285.00 Capacitor -\$15.00 Misc Material- \$20.00					
		LABOR	4.0	\$85.00	\$340.00
4HR @ 85.00 - \$340.00		MATERIAL		\$320.00	\$320.00
		20% MARK UP		\$64.00	\$64.00
		SALES TAX			
SUB-TOTAL COSTS:		Materials Total	\$384.00	Labor	\$340.00
		TOTAL	\$724.00		